



PRESSURE/TORQUE CONVERSION CHART

2HPAB
1-1/8" to 1-13/16"

PRESSURE IN PSI	FT. LBS.	N-m
1000	67	91
1200	115	156
1400	158	214
1600	184	249
1800	208	282
2000	233	316
2200	260	353
2400	288	390
2600	313	424
2800	342	464
3000	368	499
3200	396	537
3400	424	575
3600	452	613
3800	480	651
4000	509	690
4200	537	728
4400	566	767
4600	594	805
4800	623	845
5000	652	884
5200	679	921
5400	708	960
5600	737	999
5800	765	1037
6000	794	1077
6200	822	1114
6400	850	1152
6600	879	1192
6800	907	1230
7000	936	1269
7200	965	1308
7400	993	1346
7600	1022	1386
7800	1051	1425
8000	1080	1464
8200	1109	1504
8400	1138	1543
8600	1166	1581
8800	1197	1623
9000	1225	1661
9200	1257	1704
9400	1286	1744
9600	1316	1784
9800	1346	1825
10000	1379	1870

