




PRESSURE/TORQUE CONVERSION CHART

PRESSURE IN PSI	FT. LBS.	N-m	17MD
1000	1653	2241	
1200	2012	2728	
1400	2368	3211	
1600	2772	3758	
1800	3147	4267	
2000	3471	4706	
2200	3917	5310	
2400	4286	5811	
2600	4658	6315	
2800	5028	6817	
3000	5398	7319	
3200	5770	7823	
3400	6139	8324	
3600	6512	8830	
3800	6886	9336	
4000	7257	9839	
4200	7629	10344	
4400	7977	10816	
4600	8339	11307	
4800	8698	11792	
5000	9118	12362	
5200	9416	12766	
5400	9791	13274	
5600	10161	13776	
5800	10536	14285	
6000	10912	14795	
6200	11287	15303	
6400	11677	15832	
6600	12047	16333	
6800	12435	16859	
7000	12823	17385	
7200	13200	17896	
7400	13571	18400	
7600	13919	18872	
7800	14300	19388 [®]	
8000	14717	19954	
8200	15042	20395	
8400	15433	20924	
8600	15833	21466	
8800	16191	21952	
9000	16545	22432	
9200	16935	22961	
9400	17321	23484	
9600	17696	23993	
9800	18060	24487	
10000	18446	25009	



For Reference Only