



PRESSURE/TORQUE CONVERSION CHART

2HPAB
2" to 2-3/8"

PRESSURE IN PSI	FT. LBS.	N-m
1000	31	42
1200	82	111
1400	121	164
1600	144	195
1800	165	224
2000	184	249
2200	204	277
2400	225	305
2600	246	334
2800	266	361
3000	285	386
3200	305	414
3400	324	439
3600	345	468
3800	366	496
4000	386	523
4200	407	552
4400	429	582
4600	451	611
4800	473	641
5000	494	670
5200	514	697
5400	536	727
5600	558	757
5800	579	785
6000	599	812
6200	621	842
6400	643	872
6600	664	900
6800	685	929
7000	707	959
7200	729	988
7400	751	1018
7600	772	1047
7800	794	1077
8000	815	1105
8200	837	1135
8400	858	1163
8600	879	1192
8800	901	1222
9000	923	1251
9200	945	1281
9400	966	1310
9600	988	1340
9800	1011	1371
10000	1034	1402

