



PRESSURE/TORQUE CONVERSION CHART

25IBT

PRESSURE IN PSI	FT. LBS.	N-m
1500	3677	4985
1600	3922	5317
1800	4412	5982
2000	4902	6646
2200	5392	7310
2400	5881	7973
2600	6371	8638
2800	6860	9301
3000	7350	9965
3200	7844	10635
3400	8337	11303
3600	8831	11973
3800	9324	12641
4000	9818	13311
4200	10309	13977
4400	10800	14643
4600	11290	15307
4800	11781	15973
5000	12272	16638
5200	12767	17309
5400	13262	17981
5600	13756	18650
5800	14251	19322
6000	14746	19993
6200	15246	20671
6400	15746	21348
6600	16246	22026
6800	16746	22704
7000	17246	23382
7200	17740	24052
7400	18235	24723
7600	18729	25393
7800	19224	26064
8000	19718	26734
8200	20210	27401
8400	20703	28069
8600	21195	28736
8800	21688	29405
9000	22180	30072
9200	22653	30713
9400	23126	31354
9600	23600	31997
9800	24073	32638
10000	24550	33285

